

EXHIBIT 1

ENVIRONMENTAL HAZARDS SERVICES, INC.

7469 WHITE PINE ROAD - RICHMOND, VA 23237

804-275-4788 FAX 804-275-4907

BULK ASBESTOS SAMPLE ANALYSIS SUMMARY

CLIENT: Environmental Health & Safety
P.O. Box 641172
Washington State University
Pullman, WA 99164

DATE OF RECEIPT: 30 MAR 1998
DATE OF ANALYSIS: 30 MAR 1998
DATE OF REPORT: 30 MAR 1998


EHS PROJECT #: 03-98-3108
PROJECT:

EHS SAMPLE #	CLIENT SAMPLE #/ LABORATORY GROSS DESCRIPTION	% ASBESTOS	OTHER MATERIALS
01	EHS-980018A/ White Fib.	10% Chrysotile 10% Total Asbestos	90% Non-Fibrous
02	EHS-980018B/ White Fib.	10% Chrysotile 10% Total Asbestos	90% Non-Fibrous
03	EHS-980018C/ White Fib.	10% Chrysotile 10% Total Asbestos	90% Non-Fibrous

METHOD: Polarized Light Microscopy, EPA Method 600/R-93/116

ANALYST: Mark Case

Reviewed By Authorized Signatory:

- 
☒ Howard Varner, Laboratory Director; or
☐ Irma Faszewski, Quality Assurance Coordinator; or
☐ David Xu, M.S., Senior Chemist; or
☐ Feng Jiang, M.S., Senior Geologist

Results represent the analysis of samples submitted by the client. Sample location, description, area, volume, etc., was provided by the client. This report cannot be used by the client to claim product endorsement by NVLAP or any agency of the U.S. Government. This report shall not be reproduced except in full, without the written consent of Environmental Hazards Services, Inc.

Environmental Hazards Services, Inc. recommends reanalysis by point count (for more accurate quantification) or Transmission Electron Microscopy (TEM), for enhanced detection capabilities) for materials regulated by the EPA NESHAP (National Emission Standards for Hazardous Air Pollutants) and found to contain less than ten percent (<10%) asbestos by polarized light microscopy (PLM). Both services are available for an additional fee.

LEGEND NAD = no asbestos detected
SCF = suspected ceramic fibers

plm1.dot/23MAR1998/ dpb

-- PAGE 01 of 01 -- END OF REPORT --

EHS 03-98-3108

3 PLM

Chain of Custody

From:

Address: Environmental Health & Safety
PO Box 641172
Washington State University
Pullman, WA 99164
Phone: 509/335-3041
FAX: 509/335-4442
Contact: Robyn Herring
Purchase Order: B135301

Project:

To:

Address: Environmental Hazards Services, Inc.
7469 White Pine Rd.
Richmond, VA, 23237
Phone: 804-275-4788
FAX: 804-275-4907

Date: March 24, 1998

Sample Number	Location	Pump #	Flow	Min	Volume	Matrix	Analysis	Turnaround
EHS-980013A to C	Bryan: 100N, Hall, 400						Asbestos	Standard
EHS-980014A to C	Bryan: 109, 206B, 304						Asbestos	Standard
EHS-980015A to C	Bryan: 404						Asbestos	Standard
EHS-980016A to C	Carpenter: 108A, 304, 404						Asbestos	Standard
EHS-980017A to C	Daggy: 12, 134, 335						Asbestos	Standard
EHS-980018A to C	Daggy: 213						Asbestos	Standard
Relinquished by: <i>Robyn Herring</i>		Received by: <i>Robyn Herring</i>	03/30/98	0830	Sampler Name & Signature Robyn Herring			
Relinquished by:		Received by:	date/time	date/time	Comments:			
Relinquished by:		Received by:	date/time	date/time				